KHM

KING'S HARBOUR MASTER PORTSMOUTH

NAVWARN No 39/21

CANCEL NAVWARN 03/21

- 1. The South Cardinal Pile C2 (VQ6 + FL1 10s) marking the southern limit of the Rudmore Channel at the eastern side of Fountain Lake has now been re-established in its correct charted position and is fully functional.
- 2. The following Portsmouth NAVWARNs remain in force: 38/21, 33/21, 28/21, 25/21, 71/20, 57/20, 44/20, 04/20, 15/19, 60/18, 75/17, 33/17, 27/14, 57/12 & 52/11.
- 3. Cancel this Navwarn 14 May 21.

Wednesday 12 May 2021