



KING'S HARBOUR MASTER PORTSMOUTH

NAVWARN No 33/24

LANGSTONE FAIRWAY BEACON UNLIT

1. Langstone Fairway Beacon (LFl.10s7m5M) in position 50 46.318N 001 01.374W is reported as unlit.
2. All mariners are to navigate with caution in the vicinity.
3. The following Portsmouth Navwarns remain in force : 28/24, 16/24, 14/24, 66/23, 63/23, 23/23, 6/23, 15/22, 57/20, 44/20, 15/19, 60/18, 75/17, 33/17, 27/14, 57/12, 52/11.